


NEW METTAL PLATE OVER THE DRAIN

We would like to inform you that the ITV Quality Department has installed **a plate to protect the drain of the bins from possible knocks or damage during transport.**



This new metal plate is fitted over the drain and must be removed when the bin is installed. The models that will be supplied with this protector will be the S130, S160 and S220 bins.

Below is an image of the label that you will find on them with the indications:



Technical Service Department

service@itv.es | +34 676 251 668